IPS

MATERIAL SAFETY DATA SHEET

Date Revised: JAN 2008 Supersedes: MAR 2005

WELD-ON Supersedes: MAR 200 Information on this form is furnished solely for the purpose of compliance with the Occupational Safety and Health Act and shall not be used for any other purpose.

IPS Corporation urges the customers receiving this Material Safety Data Sheet to study it carefully to become aware of the hazards, if any, of the product involved. In the interest of safety, you should notify your employees, agents and contractors of the information on this sheet.

SECTION I

MANUFACTURER'S NAME

IPS Corporation ADDRESS

17109 S. Main St., P.O. Box 379, Gardena, CA. 90248

Transportation Emergencies:

CHEMTREC: (800) 424-9300 **Medical Emergencies:**

3 E COMPANY (24 Hour No.) (800) 451-8346

Business: (310) 898-3300

CHEMICAL NAME and FAMILY

Mixture of Resin and Organic Solvents

TRADE NAME:

WELD-ON 66 Vinyl Cement

FORMULA: Proprietary

SECTION II HAZARDOUS INGREDIENTS

None of the ingredients below are listed as

carcinogens by IARC, NTP or OSHA CAS# APPROX % ACGIH-TLV ACGIH-STEL **OSHA-PEL** OSHA-STEL Synthetic Elastomer Resin NON/HAZ N/A N/A Methyl Ethyl Ketone (MEK) 78-93-3 71 -90* 200 PPM 300 PPM 200 PPM 300 PPM Tetrahydrofuran (THF)** 109-99-9 1 - 10 50 PPM# Skin 100 PPM 200 PPM 250 PPM

All of the constituents of Weld-On adhesive products are listed on the TSCA inventory of chemical substances maintained by the US EPA, or are exempt from that listing.

- * Title III Section 313 Supplier Notification: This product contains toxic chemicals subject to the reporting requirements of Section 313 of the Emergency Planning and Community Right-to-Know Act of 1986 and of 40CFR372. This information must be included in all MSDS's that are copied and distributed for this material.
- # Invista and BASF mfg's Acceptable Exposure Limit (AEL) guidelines for 8 hour and 12 hour TWA, Invista/BASF recommended STEL for 15 minute TWA.: 75 PPM
- **Information found in a report from the National Toxicology Program (NTP) on an inhalation study in rats and mice suggests that Tetrahydrofuran (THF) can cause tumors in animals. In the study the rats and mice were exposed to THF vapor levels up to 1800 PPM for two years (their lifetime), 6 hours/day, 5 days/week. Test results showed evidence of liver tumors in female mice and kidney tumors in male rats. No evidence of tumors was seen in female rats and male mice. There is no data linking Tetrahydrofuran exposure with cancer in humans.

BULK SHIPPING INFOR	MATION / CONTAINERS LARGER THAN ONE LITER	SPECIAL HAZARD DESIGNATIONS			
DOT Shipping Name:	Adhesive		HMIS	NFPA	HAZARD RATING
DOT Hazard Class:	3	HEALTH:	2	2	0 - MINIMAL
Identification Number:	UN 1133	FLAMMABILITY:	3	3	1 - SLIGHT
Packaging Group:	II	REACTIVITY:	0	1	2 - MODERATE
Label Required:	Flammable Liquid	PROTECTIVE			3 - SERIOUS
		EQUIPMENT:	B - H		4 - SEVERE
CUIDBING INFORMATIO					

SHIPPING INFORMATION FOR CONTAINERS LESS THAN ONE LITER

DOT Shipping Name: Consumer Commodity

DOT Hazard Class: ORM-D

B = Eye, Hand/Skin (for normal solvent-welding, small spill, clean-up activities)
 H = Eye, Hand/Skin, Respiratory Protection and Impermeable Apron (splash/immersion risks)

SECTION III - PHYSICAL DATA

APPEARANCE	ODOR	BOILING POINT (°F/°C)			
Clear, light syrupy liquid	Ketone	151 °F (67 °C) Based on first boiling component: THF			
SPECIFIC GRAVITY @ 73 °F ± 3.6 ° (23 °C ± 2 °)	VAPOR PRESSURE (mm Hg.)	PERCENT VOLATILE BY VOLUME (%)			
Typical 0.845 ± 0.040	143 mm Hg. based on first boiling	Approx: 75 - 90%			
	component, THF @ 68 °F (20 °C)				
VAPOR DENSITY (Air = 1)	EVAPORATION RATE (BUAC = 1)	SOLUBILITY IN WATER			
2.49	> 1.0	Solvent portion completely soluble in water.			
		Resin portion separates out.			

VOC STATEMENT: VOC as manufactured: 850 Grams/Liter. Maximum VOC emission per SCAQMD Rule 1168, Test Method 316A: 600 Grams/Liter.

SECTION IV - FIRE AND EXPLOSION HAZARD DATA

FLASH POINT	FLAMMABLE LIMITS	LEL	UEL
-4°F (-20°C) T.C.C. Based on THF	(PERCENT BY VOLUME)	2.0	11.8

FIRE EXTINGUISHING MEDIA

Ansul "Purple K" potassium bicarbonate dry chemical, any appropriately sized ABC dry chemical, carbon dioxide or foam extinguisher can be used for small fires. Use of a water fog by trained personnel can extinguish small/large fires.

SPECIAL FIRE FIGHTING PROCEDURES

Evacuate enclosed areas. Stay upwind. Close quarters or confined spaces require self-contained breathing apparatus, positive pressure mask or airline mask. Use of a water fog by trained personnel can extinguish small/large fires and avoid water flow or water streams/spray distributing burning material or contaminated water over a large area or into sewers or storm drains. Use water spray to cool containers, to flush spills from source of ignition and to disperse vapors.

UNUSUAL FIRE AND EXPLOSION HAZARDS

Fire hazard because of low flash point and high volatility. Vapors are heavier than air and may travel to source(s) of ignition at or near ground or lower level(s) and flash back.

SECTION V - HEALTH HAZARD DATA									
PRIMARY ROOF ENTRY:	OUTES	X	Inhalation	X	Skin Contact _	E	Eye Contact _	Ingestion	
EFFECT OF OVEREXPOSURE									
Inhalation: Skin Contact	Skin Contact: Skin irritant. Liquid contact may remove natural skin oils resulting in skin irritation. Dermatitis may occur with prolonged contact. Prolonged or widespread exposure may result in the absorption of harmful amounts of material. Overexposure may result in severe eye injury with corneal or conjuctival inflammation on contact with the liquid. Vapors slightly uncomfortable may result toxic. May cause nausea, vomiting, diarrhea. May cause mental sluggishness.								
	REPRODUC [*]		TERATOGENIC N. AP.		GENICITY EMBRY	OTOXICITY S N. AP.	ENSITIZATION N. AP.	TO PRODUCT SYNERGI	STIC PRODUCTS N. AV.
		AGGRAVATE of excessive		₹E: Individua	ls with pre-existinç		he eyes, skin d	or respiratory system ma	y have increased
Inhalation: Eye Contact:	physician. Eye Contact: Flush eyes with plenty of water for 15 minutes and call a physician. Skin Contact: Remove contaminated clothing and shoes. Wash skin with plenty of soap and water for at least 15 minutes. If irritation develops, get medical attention.						irritation develops, get		
				SECTI	ON VI - R	=ACTIVI	TY		
STABILITY	UNSTABLE			CONDITIO	ONS TO AVOID				
INCOMPATI (MATERIALS	BILITY	Caustics, am	monia, inorganio		y from heat, spark			•	
HAZARDOU	S DECOMPO	SITION PRO	DUCTS		n dioxide, hydroge				
HAZARDOU POLYMERIZ	S	MAY OCC	CUR	X	CONDITIONS	TO AVOID		and other sources of ign	ition.
		,	SECTIO	N VII -	SPILL OR				
STEPS TO BE TAKEN IN CASE MATERIAL IS RELEASED OR SPILLED Eliminate all ignition sources. Avoid breathing of vapors. Keep liquid out of eyes. Flush with large amount of water. Contain liquid with sand or earth. Absorb with sand or nonflammable absorbent material and transfer into steel drums for recovery or disposal. Prevent liquid from entering drains.									
WASTE DISPOSAL METHOD Follow local, State and Federal regulations. Consult disposal expert. Can be disposed of by incineration. Excessive quantities should not be permitted to enter drains. Empty containers should be air dried before disposing. Hazardous Waste Code (CA): 214.									
SECTION VIII - SPECIAL PROTECTION INFORMATION									
RESPIRATORY PROTECTION (Specify type) Atmospheric levels should be maintained below established exposure limits contained in Section II. If airborne concentrations exceed those limits, use of a NIOSH approved organic vapor cartridge respirator with full face-piece is recommended. The effectiveness of an air purifying respirator is limited. Use it only for a single short-term exposure. For emergency and other conditions where short-term exposure guidelines may be exceeded, use an approved positive pressure self-contained breathing apparatus.									
VENTILATION Use only with adequate ventilation. Provide sufficient ventilation in volume and pattern to keep contaminants below applicable exposure limits set forth in Section II. Use only explosion proof ventilation equipment.									
PROTECTIVE GLOVES PVA coated rubber gloves for frequent dipping/immersion. Use of latex/nitrile surgical gloves or solvent resistant barrier creme should provide adequate protection when normal solvent-cement welding practices and procedures are used for solvent welding of plastic sheet/pipe joints. EYE PROTECTION Splashproof chemical goggles, face shield, safety glasses (spectacles) with brow guards and side shields, etc. as appropriate for exposure.									
OTHER PROTECTIVE EQUIPMENT AND HYGIENIC PRACTICES Impervious apron and a source of running water to flush or wash the eyes and skin in case of contact.									
SECTION IX - SPECIAL PRECAUTIONS									
PRECAUTIONS TO BE TAKEN IN HANDLING AND STORING Store in the shade between 40 °F - 110 °F (5 °C - 43 °C). Keep away from heat, sparks, open flame and other sources of ignition. Avoid prolonged breathing of vapor. Use with adequate ventilation. Avoid contact with eyes, skin and clothing. Train employees on all special handling procedures before they work with this product.									
OTHER PRECAUTIONS Follow all precautionary information given on container label, product bulletins and our solvent cementing literature. All material handling equipment should be electrically grounded.									

The information contained herein is based on data considered accurate. However, no warranty is expressed or implied regarding the accuracy of this data or the results to be obtained from

the use thereof.

ff-d